

United States Department of the Interior
National Park Service

NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 Page 15

MAYWOOD HISTORIC DISTRICT INVENTORY

21st Avenue, North

3301 21st Avenue, North 000-5056-0003

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Craftsman, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid, brick-stretcher foundation. It is clad in asbestos siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on Tuscan columns and one-over-one vinyl-sash windows. Window and door surrounds are unmitered with a projecting sill and a cyma lintel. Other notable features include a shed-roof dormer, a wood cornice with a beaded-board soffit, shutters, and a massive two-and-a-half-story, vinyl-clad rear addition.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Contributing

3302 21st Avenue, North 000-5056-0004

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other, pre 1916**

The three-bay-wide, wood-frame dwelling rests on a solid brick foundation with a concrete coating. It is clad in a combination of German wood siding and asbestos shingles, and has a gable roof sheathed in asphalt shingles. It has two-over-two wood-sash windows. Window and door surrounds are unmitered and unmolded with a projecting sill. Two successive shed-roof additions have been built onto the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

3303 21st Avenue, North 000-5056-0005

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other, pre 1923**

The four-bay-wide, wood-frame dwelling is clad in German wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame full-width front porch on Tuscan columns and both two-over-two and six-over-six wood-sash windows. Window and door surrounds of the original building are unmitered and unmolded with a projecting sill. Other notable features include a parapet balustrade, and a series of one-story additions to the sides and rear of the original building.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3307 21st Avenue, North 000-5056-0006

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Craftsman, pre 1929**

The two-bay-wide, wood-frame dwelling rests on a solid, brick stretcher foundation, partially parged. It is clad in asbestos shingles and has a front-gable roof sheathed in asphalt shingles. It has one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill and lintel. Other notable features include a wood cornice with a robust cyma molding, a blank frieze, and gable returns. A single-cell vestibule has been added to the front elevation, and a shed-roof addition to the east elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 16

3310 21st Avenue, North 000-5056-0007

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in simulated-brick siding and has a cross-gable roof sheathed in standing-seam metal. It has a one-story, two-bay, wood-frame front porch on molded square posts and six-over-six wood-sash windows. Window and door surrounds are unmitered with a projecting sill and cyma lintel. Other notable features include simulated half-timbering in the gable end, a molded wood cornice, and a front entry with a single-light transom and board-and-batten wood shutters.

Individual Resource Status: **Single Dwelling**

Contributing

3312 21st Avenue, North 000-5056-0177

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other,**

The wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in wood siding, and has a front-gable roof sheathed in asphalt shingles. The one-story, three-bay, half-hip-roof front porch has turned posts. Windows are 1/1 wood-sash set off by wood surrounds with a projecting sill and beaded lintel, and one single-light fixed-sash. Other notable features include a three-faceted bay window, tall side dormers, projecting eaves with a wood soffit, a raised basement, and wood shingles in the front gable end.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Garage**

Non-Contributing

3316 21st Avenue, North 000-5056-0008

Primary Resource Information: **Single Dwelling, Stories 3, Style: Bungalow/Craftsman, pre 1916**

The two-bay-wide, wood-frame dwelling rests on a solid foundation parged with concrete and has a front-gable roof clad in asphalt shingles. It is sheathed in lapped wood siding on the first story and wood shingles on the second story. It has a one-story, two-bay, wood-frame front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are unmitered and unmolded with a projecting sill. Other notable features include wide, overhanging eaves with exposed scroll-sawn rafter tails, wood louvered shutters, and an entry with diamond-pane sidelights with stained-glass glazing. Additions include a shed-roof extension to the southeast corner, raising of the first-story bay to two stories, and a single-cell, shed-roof addition to the roof.

Individual Resource Status: **Single Dwelling**

Contributing

3400 21st Avenue, North 000-5056-0009

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, ca 1930**

The two-bay-wide, wood-frame dwelling rests on a solid brick foundation. It is clad in asbestos shingles, with vinyl siding on the side dormers, and has a front-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wrap-around wood-frame front porch on square Tuscan posts and six-over-six wood-sash windows. Window and door surrounds are molded with a thin projecting sill. Other notable features include a wood molded cornice with scroll-sawn cornice returns.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3401 21st Avenue, North 000-5056-0010

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1916**

The two-bay-wide, wood-frame dwelling rests on a solid, rock-face concrete-block foundation. It is clad in narrow, lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and one-over-one vinyl sash windows. Window and door surrounds are unmitered with a projecting sill and a cyma lintel. Other notable features include prominent gable-roof dormers with gable returns, molded wood cornice with a blank frieze, and louvered wood shutters. A two-story, single-pile addition had been built onto the rear of the building.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Playhouse**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 17

3402 21st Avenue, North 000-5056-0011

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other, pre 1923**

The two-bay-wide, wood-frame dwelling is clad in a combination of aluminum siding and wood shingles, and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on turned round posts, and six-over-one wood-sash windows. Window and door surrounds are beaded with a projecting sill. Other notable features include wide, overhanging eaves with paired brackets and a beaded board soffit, a bay window on the east elevation, and a hipped front dormer.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Shed**

Contributing

Non-Contributing

3405 21st Avenue, North 000-5056-0012

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1912**

The four-bay-wide, wood-frame dwelling rests on a solid foundation, and is clad in lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wrap-around wood-frame front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds have a molded cyma lintel. Other notable features include a hip-roof dormer on each elevation, a flared roof with wide, overhanging eaves and exposed scroll-sawn rafter tails, and an addition with a massive brick chimney to the west elevation.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Garage**

Contributing

Contributing

3406 21st Avenue, North 000-5056-0013

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1917**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in aluminum siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on round turned posts and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill and a molded lintel. Other notable features include an unmolded wood cornice with beaded-board in the soffit, gable returns, and a shed-roof addition to the rear.

Individual Resource Status: **Single Dwelling**

Contributing

3409 21st Avenue, North 000-5056-0014

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The three-bay-wide, wood-frame dwelling is clad in asbestos shingles and has a front-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, concrete-block front porch with a flat roof and one-over-one wood-sash windows. Window and door surrounds are unmolded. Other notable features include wide, overhanging eaves with gable returns, and an entry with a five-light transom and five-light sidelights.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Garage**

Contributing

Contributing

3411 21st Avenue, North 000-5056-0175

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The brick dwelling rests on a solid poured concrete foundation. It is faced with stretcher bond, and has a side-gable roof sheathed in asphalt shingles. The one-story, three-bay, half-hip-roof front porch has square posts with flat recessed panels. Windows are 6/6 and 1/1 vinyl-sash, with a single fixed plate glass picture window on the first story. Other notable features include a three-faceted bay window on the first story, rowlock sills, simulated louvered shutters, and a wood door surround with fluted pilasters.

Individual Resource Status: **Single Dwelling**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 18

3412 21st Avenue, North 000-5056-0015

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1912**

The wood-frame dwelling rests on a solid foundation, and is clad in weatherboard and has a compound gable roof sheathed in pressed metal sheets. It has a one-story, three-bay, wrap-around wood-frame front porch on turned posts supported by parged piers, and featuring wood brackets. It has one-over-one wood-sash windows, and window and door surrounds feature molded lintels. Other notable features include fishscale wood shingles in the front gable end and gable returns, and additions on the east and south elevations.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3415 21st Avenue, North 000-5056-0016

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1916**

The three-bay-wide, wood-frame dwelling rests on a solid foundation. It is clad in lapped wood siding and has a cross-gable roof sheathed in pressed metal sheets. It has a one-story, three-bay, wood-frame front porch on turned posts and one-over-one wood-sash windows. Window and door surrounds have molded lintels. Other notable features include wide, overhanging eaves, wood fishscale shingles in the gable ends, and a large rear addition.

Individual Resource Status: **Single Dwelling**

Contributing

3420 21st Avenue, North 000-5056-0017

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1912**

The three-bay-wide, wood-frame dwelling rests on a solid foundation. It is clad in weatherboard and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on columns and one-over-one wood-sash windows. Window and door surrounds feature molded lintels. Other notable features include a hip-roof dormer, wide, overhanging eaves, and a one-story screened-in porch addition on the rear of the building.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3421 21st Avenue, North 000-5056-0018

Primary Resource Information: **Single Dwelling, Stories 1, Style: Colonial Revival, pre 1932**

The three-bay-wide, brick dwelling rests on a solid American bond brick foundation. Likely of wood-frame construction with a brick veneer exterior, the building has a side-gable roof sheathed in asphalt shingles. It has a one-story, single-bay wood-frame portico on paired square posts, and six-over-six wood-sash windows. Windows feature rowlock sills and soldier-course lintels. Other notable features include a one-story porch on the west elevation, a molded wood cornice with gable-end returns, and a one-story wood-frame rear addition clad in vinyl siding.

Individual Resource Status: **Single Dwelling**

Contributing

3424 21st Avenue, North 000-5056-0019

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1914**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in weatherboard and has a hipped roof sheathed in asphalt shingles. It has a one-story, four-bay, wood-frame wrap-around front porch on posts and one-over-one wood-sash windows. Window and door surrounds have molded lintels. Other notable features include a hip-roof dormer and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 19

3500 21st Avenue, North 000-5056-0020

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1912**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in weatherboard and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame wrap-around front porch on columns and one-over-one wood-sash windows. Window and door surrounds have molded lintels. Other notable features include a gable-roof dormer and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

3501 21st Avenue, North 000-5056-0021

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in weatherboard and has a hipped roof sheathed in pressed metal shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and one-over-one paired wood-sash windows. Window and door surrounds have a molded lintel. Other notable features include a hip-roof dormer and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

3504 21st Avenue, North 000-5056-0022

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is currently being renovated and is awaiting the application of siding. It has a hipped roof sheathed in asphalt shingles, and a one-story, two-bay, wood-frame front porch on square turned posts and one-over-one wood-sash windows. Window and door surrounds are unmitered and unmolded with a flush sill and a projecting rounded lintel. Other notable features include a hip-roof dormer, craftsman brackets, and a large, two-story bay window addition on the east elevation.

Individual Resource Status: **Single Dwelling**

Contributing

3505 21st Avenue, North 000-5056-0023

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in lapped wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on turned posts and one-over-one wood-sash windows. Window and door surrounds have molded lintels. Other notable features include wide, overhanging eaves, diamond wood shingles and gable returns in the gable ends, and louvered shutters.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3508 21st Avenue, North 000-5056-0024

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, ca 1912**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in asbestos shingles and has a hipped roof sheathed in pressed metal shingles. It has a one-story, three-bay, wood-frame front porch on turned posts and one-over-one wood-sash windows. Window and door surrounds have molded lintels. Other notable features include a hip-roof dormer, wide, overhanging eaves, and a one-story, hip-roof addition on the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 20

3509 21st Avenue, North 000-5056-0025

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1927**

The two-bay-wide, wood-frame dwelling rests on a solid, rock-face concrete-block foundation. It is clad in stretcher-bond brick veneer on the first story, and asbestos shingles on the second story, and has a side-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, rock-face concrete-block and brick front porch on square posts and both six-over-one and one-over-one wood-sash windows. Window and door surrounds on the first story feature robust concrete lintels. Other notable features include a gable-roof dormer, and wide, overhanging eaves with exposed rafters tails.

Individual Resource Status: **Single Dwelling**

Contributing

3601 21st Avenue, North 000-5056-0026

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1916**

The two-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in wood shingles on the first story and asbestos shingles on the second story, and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch clad in asbestos shingles. Windows are six-over-one, six-over-six, and one-over-one wood-sash with unmolded surrounds. Other notable features include a rear extension to the building.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Contributing

3602 21st Avenue, North 000-5056-0027

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1923**

The four-bay-wide, wood-frame dwelling with a solid foundation. It is clad in weatherboard and has a hipped roof sheathed in standing-seam metal. It has a one-story, three-bay, wood-frame wrap-around front porch on turned posts and two-over-two wood-sash windows. Window and door surrounds are unmolded. Other notable features include wide, overhanging eaves and a three-faceted bay window on the east elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

3605 21st Avenue, North 000-5056-0028

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1912**

The two-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in weatherboard and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on square posts and one-over-one wood-sash windows. Other notable features include fishscale shingles and molded gable-returns in the front gable end. A large, gable-roof addition has been built onto the east elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3606 21st Avenue, North 000-5056-0029

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1939**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in aluminum siding and has a side-gable roof sheathed in asphalt shingles. It has six-over-six wood-sash windows, and window and door surrounds are molded on the first story. Other notable features include two gable-roof dormers, a one-story gable-roof portico of the front entry, and an addition to the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 21

3609 21st Avenue, North 000-5056-0030

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The two-bay-wide, wood-frame dwelling clad in vinyl siding and has a hipped roof sheathed in standing-seam metal. It has a one-story, two-bay, wood-frame front porch on turned square posts and one-over-one wood-sash windows. Other notable features include wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

3610 21st Avenue, North 000-5056-0031

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in asbestos siding and has a hipped roof sheathed in standing-seam metal. It has a one-story, two-bay, wood-frame front porch on turned square posts, with a standing-seam copper roof. It has two-over-two wood-sash windows. Other notable features include a hip-roof dormer and a two-story brick addition to the east elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3613 21st Avenue, North 000-5056-0032

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1916**

The two-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in asbestos shingles and has a hipped roof sheathed in standing-seam metal. It has a one-story, two-bay, wood-frame front porch on turned square posts and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill. Other notable features include a hip-roof dormer, wide, overhanging eaves, and a one-story addition to the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3616 21st Avenue, North 000-5056-0033

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, ca 1910**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in German wood siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on round turned posts with a standing-seam metal roof. Windows are one-over-one wood-sash windows on the first story and single hinged two-light wood-sash windows in the dormers. Window and door surrounds are unmitered with a projecting sill and molded lintel. Other notable features include two hip-roof dormers and a deck off the rear.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

3620 21st Avenue, North 000-5056-0034

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1918**

The three-bay-wide, wood-frame dwelling is clad in flush weatherboard and has a cross-gable roof sheathed in asphalt shingles. Window and door surrounds are mitered and molded with a projecting sill. Other notable features include a wood pergola supported on a brick masonry wall on the north elevation, a molded wood cornice, aluminum simulated shutters, and large, two-story additions on the east and rear elevations.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 22

3621 21st Avenue, North 000-5056-0035

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1923**

The two-bay, wood-frame dwelling rests on a solid parged foundation. It is clad in aluminum siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on columns and one-over-one wood-sash windows. Window and door surrounds feature a molded lintel. Other notable features include wide, overhanging eaves, two gable-roof side dormers, and a large rear addition.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3623 21st Avenue, North 000-5056-0036

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other, pre 1923**

The three-bay, wood-frame dwelling rests on a solid brick foundation. It is clad in asbestos shingles and has a side-gable roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame front porch on square posts and one-over-one vinyl-sash windows. Window and door surrounds are unmitered with a projecting sill. Other notable features include aluminum siding on the cornice and window and door surrounds, wide, overhanging eaves, a diamond-shaped vent in the front gable peak, and a large addition onto the rear.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3624 21st Avenue, North 000-5056-0037

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1918**

The two-bay-wide, wood-frame dwelling is clad in lapped wood siding and has a compound hipped roof sheathed in standing-seam metal. A two-story ell projects from the west elevation. The building has a one-story, four-bay, wood-frame front porch on round turned posts with a wood pergola roof, and both one-over-one and six-over-one wood-sash windows. Window and door surrounds are unmolded and unmitered with a projecting sill. Other notable features include a hip-roof dormer, a wood box cornice, and a new front vestibule and west-side pergola.

Individual Resource Status: **Single Dwelling**

Contributing

3628 21st Avenue, North 000-5056-0170

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1929**

The three-bay-wide, wood-frame dwelling is clad in vinyl siding, and has a side-gable roof sheathed in asphalt shingles. The one-story, five-bay, shed-roof front porch has square posts. Windows are 1/1 vinyl-sash. Other notable features include simulated louvered shutters, projecting eaves, and a vinyl soffit and cornerboards. The house was completely rebuilt c.1985.

Individual Resource Status: **Single Dwelling**

Non-Contributing

3629 21st Avenue, North 000-5056-0038

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1916**

The wood-frame dwelling rests on a solid parged foundation. It is clad in weatherboard and has a gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on turned posts and two-over-two wood-sash windows. Other notable features include wide, overhanging eaves and a one-story addition on the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 23

3630 21st Avenue, North 000-5056-0039

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1917**

The two-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in lapped and German wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on turned square posts and two-over-two wood-sash windows. Window and door surrounds are unmitered with a projecting sill and a molded lintel. Other notable features include turned balusters on the front porch, hinged louvered wood shutters, diamond wood shingles and a semi-circular fanlight in the gable end, and a molded cornice with gable returns. A large, two-story addition has been built onto the rear of the building.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

22nd Street, North

2901 22nd Street, North 000-5056-0040

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1916**

The two-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in vinyl siding and has a hipped roof sheathed in asphalt shingles. It has an enclosed one-story wood-frame front porch. Windows are one-over-one wood-sash, one-over-one vinyl-sash, and one-by-one horizontal sliding-sash. Other notable features include a hip-roof dormer, and several shed additions which feature wood craftsman-style brackets.

Individual Resource Status: **Single Dwelling**

Contributing

2904 22nd Street, North 000-5056-0041

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has an enclosed one-story, two-bay, wood-frame front porch. Window and door surrounds are beaded. Other notable features include a hip-roof dormer, wide, overhanging eaves and a shouldered brick exterior end chimney.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

Individual Resource Status: **Shed**

Contributing

2905 22nd Street, North 000-5056-0042

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne,**

The four-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in vinyl siding and has a gable roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame front porch on square posts and one-over-one vinyl-sash windows. Other notable features include a wood cornice with dentils.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2908 22nd Street, North 000-5056-0043

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The three-bay-wide, wood-frame dwelling rests on a solid foundation. It is clad in weatherboard and has a gable roof sheathed in asphalt shingles. It has a one-story, four-bay, wood-frame front porch on columns and one-over-one wood-sash windows. Window and door surrounds are beaded. Other notable features include wide, overhanging eaves, and a metal standing-seam roof on the porch.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

Individual Resource Status: **Playhouse**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 24

2911 22nd Street, North 000-5056-0044

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1937**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in asbestos shingles and has a gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on square posts clad in asbestos shingles, and six-over-six wood-sash windows. Window and door surrounds are unmolded and unmitered, with a projecting sill and lintel. Other notable features include side dormers, a molded wood cornice, and a single-cell addition to the east of the front porch.

Individual Resource Status: **Single Dwelling**

Contributing

2912 22nd Street, North 000-5056-0045

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1927**

The two-bay-wide, wood-frame dwelling rests on a solid parged-brick foundation. It is clad in weatherboard and wood shingles and has a hipped roof sheathed in pressed metal shingles. It has a one-story, two-bay, wood-frame front porch on Tuscan posts and both six-over-one and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill. Other notable features include a hip-roof dormer, wide, overhanging eaves and a parapet balustrade on the porch.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Contributing

2915 22nd Street, North 000-5056-0046

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1918**

The three-bay-wide wood-frame dwelling rests on a solid parged foundation. It is clad in vinyl siding and has a front-gable roof sheathed in pressed metal shingles. It has a one-story, two-bay, wood-frame wrap-around front porch on columns and one-over-one vinyl-sash windows. Other notable features include fishscale wood shingles in the front gable-end, a large side dormer, wide, overhanging eaves, and a one-story, shed-roof addition to the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3200 22nd Street, North 000-5056-0047

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1915**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in weatherboard and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on brick posts and six-over-one wood-sash windows. Window and door surrounds have tapered vertical elements. Other notable features include wide, overhanging eaves with exposed scroll-sawn rafter tails.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3201 22nd Street, North 000-5056-0048

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The three-bay-wide, wood-frame dwelling rests on a solid parged-brick foundation. It is clad in vinyl siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story wood-frame wrap-around front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are aluminum and feature molded drip lintels. Other notable features include two gable-roof front dormers, wide, overhanging eaves, and an aluminum cornice.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 25

3205 22nd Street, North 000-5056-0049

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in German vinyl siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story wrap-around wood-frame front porch on Tuscan columns. Windows are vinyl-sash eight-over-eight, six-over-six and four-over-four. Window and door surrounds are unmolded. Other notable features include wide, overhanging eaves and an aluminum cornice.

Individual Resource Status: **Single Dwelling**

Contributing

3206 22nd Street, North 000-5056-0050

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1916**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in weatherboard and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columned and one-over-one aluminum-sash windows. Window and door surrounds have molded lintels. Other notable features include three hip-roof dormers.

Individual Resource Status: **Single Dwelling**

Contributing

3208 22nd Street, North 000-5056-0051

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1916**

The three-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in weatherboard and has a hipped roof, and a one-story, three-bay, wood-frame front porch on Tuscan columns. It has one-over-one wood-sash windows. Other notable features include a hip-roof dormer and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

Individual Resource Status: **Shed**

Non-Contributing

3210 22nd Street, North 000-5056-0052

Primary Resource Information: **Park,**

The park features a playground area with slides, swings, and other equipment fenced with vertical wood boards. A sidewalk leads to a paved area with benches. The street side of the park is set off by a wood fence, and the rear of the lot blocked by a net fence.

Individual Resource Status: **Park**

Non-Contributing

3211 22nd Street, North 000-5056-0053

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1912**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in weatherboard and has a side-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on posts. Windows are of several types include ten-over-one and six-over-one wood-sash, and four-light wood-sash casement windows in the dormers. Window and door surrounds are beaded. Other notable features include a gable-roof dormer clad in wood shingles, wide, overhanging eaves, and a solid brick balustrade.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3215 22nd Street, North 000-5056-0054

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1929**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in aluminum siding and has a side-gable roof sheathed in asphalt shingles. It has a shed-roof portico on the front elevation supported on metal posts, and six-over-six wood-sash windows. Other notable features include wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 26

3301 22nd Street, North 000-5056-0056

Primary Resource Information: **Single Dwelling, Stories 2, Style: Dutch Colonial, pre 1912**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is stuccoed on the exterior and has a front-gambrel roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on paneled posts and both six-over-one and one-over-one wood-sash windows. Window and door surrounds are unmolded. Other notable features include a side shed-roof dormer, paneled pilasters, a molded wood cornice, a built-in bench on the front porch and a leaded-glass transom over the front entry.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3302 22nd Street, North 000-5056-0055

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1916**

The two-bay-wide, wood-frame dwelling rests on a solid foundation. It is clad in vinyl siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, metal front porch on wrought-iron posts and six-over-six wood-sash windows. Window and door surrounds are narrow and molded. Other notable features include two shed-roof side dormers.

Individual Resource Status: **Single Dwelling**

Contributing

3305 22nd Street, North 000-5056-0057

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The four-bay-wide, wood-frame dwelling rests on a solid foundation. It is clad in a combination of brick veneer and aluminum siding, and has a front-gable roof sheathed in asphalt shingles. It has a one-story front portico on metal posts and both multi-light vinyl fixed-sash and one-over-one vinyl-sash windows. Other notable features include wide, overhanging eaves and a balcony on the second floor.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Shed**

Non-Contributing

3308 22nd Street, North 000-5056-0058

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1923**

The two-bay-wide, wood-frame dwelling clad in lapped wood siding with has a hipped roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame wrap-around front porch on Tuscan columns and one-over-one wood-sash windows. Two casement windows are also present, one with two-over-two sashes and one with six-over-six sashes. Window and door surrounds are unmolded. Other notable features include a hip-roof dormer, wide, overhanging eaves and a bay window. A porch has been added to the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

3309 22nd Street, North 000-5056-0059

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1930**

The three-bay-wide, wood-frame dwelling rests on a solid foundation. It is stuccoed and has a jerkinhead roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on square posts and eight-over-one wood-sash windows. Window and door surrounds are unmolded. Other notable features include wide, overhanging eaves with exposed rafter tails, and one-story, hip-roof addition.

Individual Resource Status: **Single Dwelling**

Contributing

3313 22nd Street, North 000-5056-0060

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1912**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is stuccoed and has a gable-roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on round turned posts and one-over-one wood-sash windows. Window and door surrounds are unmitered wood with a projecting sill and molded lintel. Other notable features include sawn brackets on the porch, a diamond-paned window on the east elevation, and a one-story addition to the rear.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 27

3314 22nd Street, North 000-5056-0061

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1947**

The three-bay-wide, concrete-block masonry dwelling has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on turned posts and six-over-six wood and vinyl-sash windows. Other notable features include a one-story addition to the west elevation.

Individual Resource Status: **Single Dwelling**

Non-Contributing

3318 22nd Street, North 000-5056-0062

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1923**

The wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is stuccoed and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on replacement posts and one-over-one wood-sash windows. Other notable features include wide, overhanging eaves and a one-story shed-roof addition with a concrete-block foundation and clad in stucco.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3319 22nd Street, North 000-5056-0063

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1929**

The two-bay-wide, wood-frame dwelling rests on a solid parged brick foundation. It is clad in lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on turned posts and one-over-one wood-sash windows. Window and door surrounds feature a molded lintel and projecting sills. Other notable features include a hip-roof dormer and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

3327 22nd Street, North 000-5056-0064

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1937**

The three-bay-wide, likely wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in brick veneer and has a side-gable roof sheathed in asphalt shingles. It has a short, one-story wood-frame portico on square posts and one-over-one vinyl-sash windows with rowlock sills and soldier lintels. Other notable features include two gable-roof dormers on the front elevation, an arched rowlock door surround, a semi-circular vent in the central portico, simulated louvered wood shutters, and a one-story wood-frame sun-room on the west elevation with a parapet balustrade. The front dormers and wide, rear shed-roof dormer appear to be new additions.

Individual Resource Status: **Single Dwelling**

Contributing

3500 22nd Street, North 000-5056-0065

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1912**

The four-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is stuccoed and has a hipped roof sheathed in asphalt shingles. It has six-over-one wood-sash windows, and molded window and door surrounds. Other notable features include hipped dormers on each elevation, wide, overhanging eaves, and a small hipped hood over the main entry.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3501 22nd Street, North 000-5056-0066

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1911**

The two-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in narrow lapped wood siding and has a cross-hip roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame wrap-around front porch on columns and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill and a molded lintel. Other notable features include a hip-roof dormer, wide, overhanging eaves, hinged wood louvered shutters, and a wood cornice with beaded-board soffit.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 28

3504 22nd Street, North 000-5056-0067

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in asbestos shingles and has a hipped roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on turned posts and one-over-one wood-sash windows. Window and door surrounds feature molded lintels. Other notable features include a hip-roof dormer, wide, overhanging eaves and a one-story addition on the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

3505 22nd Street, North 000-5056-0068

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The three-bay-wide, wood-frame dwelling is clad in asbestos shingles and has a hipped roof sheathed in pressed metal shingles. It has a one-story, four-bay, wood-frame wrap-around front porch on Tuscan columns and nine-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill and a molded lintel. Other notable features include a hip-roof dormer with a single hinged sash with diamond panes, a bay window on the east elevation, a standing-seam metal roof on the porch, and a beaded-board in the soffit.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3508 22nd Street, North 000-5056-0069

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1918**

The three-bay-wide, wood-frame dwelling rests on a solid concrete block foundation. It is clad in asbestos shingles and has a side-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on posts and one-over-one wood-sash windows. Window and door surrounds feature molded lintels. Other notable features include a shed-roof dormer, wide, overhanging eaves with exposed scroll-sawn rafter tails, and a one-story addition to the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3511 22nd Street, North 000-5056-0070

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in asbestos shingles and has a front-gable roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame gabled portico on square posts and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill and molded lintels. Other notable features include hinged wood louvered shutters, a large shed-roof addition to the east elevation and several shed-roof additions to the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

3600 22nd Street, North 000-5056-0071

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1912**

The wood-frame dwelling rests on a solid parged foundation. It is clad in weatherboard and has a compound gable roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame front porch on columns and both one-over-one and nine-over-one wood-sash windows. Window and door surrounds have molded lintels. Other notable features include a polygonal front elevation, wide, overhanging eaves with a beaded-board soffit, fishscale shingles and gable returns in the gable ends, and several additions on the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 29

3602 22nd Street, North 000-5056-0072

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1929**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in vinyl siding and has a front-gable roof sheathed in asphalt shingles. It has a two-story, three-bay, screened-in wood-frame front porch on posts and both one-by-one vinyl casement windows and one-over-one vinyl-sash windows. Other notable features include a wide, overhanging eaves, an aluminum-clad cornice, and several additions to the rear elevation.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Shed**

Non-Contributing

3603 22nd Street, North 000-5056-0073

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1912**

The two-bay-wide, wood-frame dwelling is clad in narrow lapped wood siding and has a hipped roof sheathed in pressed metal shingles. It has a one-story, three-bay, wood-frame wrap-around front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill and molded lintel. Other notable features include a hip-roof dormer, wide, overhanging eaves with a smooth wood soffit and scroll-sawn brackets, and a large rear addition.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3607 22nd Street, North 000-5056-0074

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other, pre 1929**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is stuccoed and has a hipped roof sheathed in slate shingles. It has a one-story, three-bay, stuccoed wood-frame front porch on square posts and replacement aluminum sash windows. Window and door surrounds are beaded and unmitered with a projecting sill. Other notable features include an aluminum box cornice and a one-story shed-roof addition to the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3610 22nd Street, North 000-5056-0075

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The three-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in aluminum siding and has a hipped roof sheathed in standing-seam metal. It has a one-story, two-bay, wood-frame front porch on square posts and one-over-one wood-sash windows. Window and door surrounds feature a molded lintel. Other notable features include a hip-roof dormer clad in vinyl siding, wide, overhanging eaves and one-story additions to the east and rear elevations.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3614 22nd Street, North 000-5056-0076

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1929**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in asbestos shingles and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on turned posts and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill. Other notable features include a gable-roof front dormer and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 30

3618 22nd Street, North 000-5056-0077

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1929**

The four-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in weatherboard and has a hipped roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame front porch on turned posts and six-over-six, four-over-one, and one-over-one wood-sash windows. Other notable features include a gable-roof dormer with gable returns, wide, overhanging eaves with exposed scroll-sawn rafter tails, and a one-story extension on the front elevation.

Individual Resource Status: **Single Dwelling**

Contributing

3623 22nd Street, North 000-5056-0078

Primary Resource Information: **Single Dwelling, Stories 1, Style: Bungalow/Craftsman, pre 1929**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is coated in stucco and has a side-gable roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame front portico on Tuscan columns and six-over-one wood-sash windows. Window and door surrounds are unmitered with a molded backband and a projecting sill. Other notable features include a wide, overhanging eaves with exposed rafter tails, triangular craftsman-style brackets in the gable ends, and a beaded-board soffit.

Individual Resource Status: **Single Dwelling**

Contributing

3624 22nd Street, North 000-5056-0079

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other, pre 1923**

The four-bay-wide, wood-frame dwelling rests on a solid parged foundation and is clad in vinyl siding. It consists of the original section with a hipped roof, and a recent addition with a side-gable roof, both sheathed in asphalt shingles. It has a one-story, five-bay, wood-frame front porch on turned posts and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill. Other notable features include a hip-roof dormer, wide, overhanging eaves, a large addition to the west elevation of the original building, and an addition to the rear of the original building.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

3629 22nd Street, North 000-5056-0080

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1923**

The two-bay-wide dwelling, likely wood-frame, rests on a solid foundation with a perma-stone coating. It is clad in perma-stone and has a front-gable roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame front porch on tapered square bungalow columns clad in perma-stone, and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill and a molded backband. Other notable features include wide, overhanging eaves with triangular craftsman-style brackets.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Outbuilding**

Contributing

3630 22nd Street, North 000-5056-0081

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1929**

The three-bay-wide masonry dwelling rests on a solid rock-face concrete-block foundation. The material of construction appears to be either rough-cast concrete block or over-sized brick. It has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on square posts and six-over-one vinyl-sash windows. Other notable features include a gable-roof front dormer clad in lapped wood siding, wide, overhanging eaves, a brick water table, quoining around the first-story windows, and a rear two-story addition.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 31

23rd Road, North

2725 23rd Road, North 000-5056-0107

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1916**

The three-bay-wide, wood-frame dwelling is clad in weatherboard and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on posts and both nine-over-one and six-over-one wood-sash windows. Other notable features include a gable-roof front dormer with three six-over-one wood-sash windows, and wide, overhanging eaves with exposed rafter tails.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

2729 23rd Road, North 000-5056-0108

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The three-bay-wide, wood-frame dwelling rests on a solid stucco foundation. It is partially stuccoed and partially clad in plywood simulating vertical boards, and has a shallow side-gable roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame arched front portico on Tuscan columns and one-light vinyl casement windows. Other notable features include a built-in garage and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2733 23rd Road, North 000-5056-0109

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1929**

The three-bay-wide dwelling rests on a solid brick stretcher foundation. It is clad in 5-course American bond brick and has a side-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, brick front porch on square brick posts and six-over-one wood-sash windows. A continuous soldier beltcourse serves the lintels for the windows, which also feature solid, concrete projecting sills. Other notable features include a shed-roof front dormer with three six-over-one wood-sash windows, wide, overhanging eaves with exposed rafter tails, a three-faceted bay window on the east elevation.

Individual Resource Status: **Single Dwelling**

Contributing

2737 23rd Road, North 000-5056-0110

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1916**

The two-bay-wide, wood-frame dwelling is clad in wood shingles and has a front-gable roof with flared eaves, sheathed in asphalt shingles. It has a one-story, four-bay, wood-frame wrap-around front porch on Tuscan columns. Windows are a one-over-one wood sash and one-over-one vinyl-sash, with one-light single-sash in the gable end. Other notable features include wide, overhanging eaves with a beaded soffit, a three-faceted bay window on the west elevation, two gable-roof dormers on the side elevations, and an entry with a four-light transom and two-light sidelights. Also of note is an electrified lamp on a turned wood post. The metal lantern appears to have originally been gas-burning.

Individual Resource Status: **Single Dwelling**

Contributing

2801 23rd Road, North 000-5056-0111

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1935**

The three-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in narrow lapped wood siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and six-over-one wood-sash windows. Window and door surrounds are beaded. Other notable features include a front-gable front dormer with three six-over-one wood-sash windows, wide, overhanging eaves, and applied louvered simulated shutters.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 32

2836 23rd Road, North 000-5056-0189

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The three-bay-wide, concrete-block masonry dwelling rests on a solid brick stretcher foundation. On the first story it is faced with brick stretcher bond, and on the second story it is clad in vinyl siding. It has a side-gable roof sheathed in wood shingles. Windows are 8/8 and 6/6 vinyl-sash, with 2 fixed single-light vinyl picture windows on the first story. Other notable features include rowlock sills on the first story, paired doors with flaking single-light sidelights, projecting eaves on the facade, and a rowlock string course. The second story projects over the first on the front and rear elevations. Major alterations include the addition of the second story and the rear deck.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Playhouse**

Non-Contributing

2837 23rd Road, North 000-5056-0112

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1916**

The three-bay-wide dwelling rests on a solid stucco foundation. It is stuccoed and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on square posts and paired six-over-one wood-sash windows. Window and door surrounds are narrow with a projecting sill. Other notable features include a front-gable-roof dormer with four six-over-one wood-sash windows, wide, overhanging eaves with triangular knee braces, and a one-story rear addition clad in vinyl siding.

Individual Resource Status: **Single Dwelling**

Contributing

3309 23rd Road, North 000-5056-0182

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival,**

The three-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. It is faced with brick stretcher veneer, and aluminum siding on the dormer and portico. The one-story, single-bay portico has aluminum columns. Windows are 6/6 wood-sash, set off by projecting rowlock sills. Other notable features include a wide, shed-roof dormer, and unmolded wood window surrounds.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Shed**

Non-Contributing

3310 23rd Road, North 000-5056-0113

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1937**

The four-bay-wide dwelling rests on a solid brick foundation. It is clad in six-course American bond brick and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on square posts and six-over-six vinyl-sash replacement windows. Window and door surrounds are set within the brick on the first story. Other notable features include vinyl siding in the gable ends, applied simulated louvered shutters, and a full-height window in the second bay of the front elevation which appears to have originally been a door.

Individual Resource Status: **Single Dwelling**

Contributing

3312 23rd Road, North 000-5056-0181

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in weatherboard, and has a side-gable roof sheathed in asphalt shingles. The one-story, three-bay, shed-roof front porch has turned posts. Windows are 1/1 wood-sash, set off by unmolded wood surrounds. Other notable features include projecting eaves.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Shed**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 33

3320 23rd Road, North 000-5056-0114

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1935**

The two-bay-wide, wood-frame vernacular dwelling is clad in weatherboard and has a steeply-sloping side-gable roof sheathed in asphalt shingles. It has a one-story, single-bay, shed-roof wood-frame front porch on square posts and a variety of different window types including diamond-pane wood sash and one-by-one horizontal sliding sash windows. Other notable features include a molded wood cornice, flush eaves, a front porch enclosure and a shed-roof addition to the rear.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Shed**

Contributing

Non-Contributing

3322 23rd Road, North 000-5056-0115

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1929**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in lapped wood siding and has a jerkinhead roof sheathed in asphalt shingles. It has a one-story, single-bay, wood-frame shed-roof front porch on tapered square posts. Windows are both eight-light wood casement windows and six-over-one wood-sash windows. Window and door surrounds are unmitered and beaded with a projecting sill. Other notable features include wide, overhanging eaves with exposed rafter tails, a multi-planed front elevation, and a shed-roof addition and porch to the southeast corner.

Individual Resource Status: **Single Dwelling**

Contributing

23rd Street, North

2817 23rd Street, North 000-5056-0083

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1928**

The four-bay-wide dwelling rests on a solid stuccoed foundation. It is stuccoed and has a cross-gable roof sheathed in wood shingles. It has six-over-six, and one-over-one wood-sash windows set off by projecting stuccoed lintels. Other notable features include a projecting center bay with a bay window, two shed-roof dormers, a molded wood cornice, and wide, overhanging eaves supported on exposed rafters and medieval revival knee-braces.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Shed**

Contributing

Non-Contributing

2821 23rd Street, North 000-5056-0187

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival,**

The three-bay-wide, concrete-block masonry dwelling rests on a solid brick foundation. It is faced with 6:1 Flemish bond, and has a side-gable roof sheathed in asphalt shingles. Windows are 1x1 vinyl-sash, and there is a fixed plate glass window flanked by eight-light horizontal sliding windows. Other notable features include 2 front-gable dormers clad in vinyl siding, simulated louvered shutters, rowlock sills, a wood fascia, and a stylized Colonial Revival entry surround with a denticulated entablature.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2822 23rd Street, North 000-5056-0084

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The three-bay-wide, wood-frame dwelling is clad in lapped wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on Tuscan columns and both six-over-six and one-over-one wood-sash windows. Other notable features include fishscale shingles and gable returns in the front gable-end, wide, overhanging eaves, a carport addition to the west elevation and a large rear extension.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 34

2900 23rd Street, North 000-5056-0186

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The two-bay-wide, wood-frame dwelling rests on a solid concrete foundation molded to simulate brick. It is clad with vinyl siding, and has a front-gable roof sheathed in asphalt shingles. The one-story, two-bay, half-hip-roof front porch has Tuscan columns. Windows are 1/1 vinyl-sash set off by unmolded wood surrounds. Other notable features include a three-faceted bay window with a central fixed vinyl sash, simulated louvered shutters, wood shingles in the gable end, a wood box cornice, and an off-center entry with a single-light sidelight.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Playhouse**

Non-Contributing

2904 23rd Street, North 000-5056-0085

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Craftsman, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in wood shingles and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and both one-over-one and six-light awning wood-sash windows. Other notable features include a hip-roof dormer with tapered craftsman-style surrounds, wide, overhanging eaves, a molded wood cornice, and a front entry with a tri-partite transoms and diamond-paned sidelights above raised panels.

Individual Resource Status: **Single Dwelling**

Contributing

2907 23rd Street, North 000-5056-0086

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1923**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation and rises one-and-a-half-stories with a raised basement. It is clad in wood shingles and has a side-gable roof sheathed in standing-seam metal. It has one-over-one and one-light hinged wood-sash windows. Window and door surrounds are beaded. Other notable features include a shed-roof dormer, wide, overhanging eaves with brackets and exposed rafter tails, a battered exterior-end chimney of brick and stone masonry, and a stuccoed addition to the front elevation.

Individual Resource Status: **Single Dwelling**

Contributing

2908 23rd Street, North 000-5056-0087

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in narrow, lapped wood siding on the first story and wood shingles on the second story. It has a hipped roof sheathed in asphalt shingles, and a one-story, two-bay, wood-frame front porch on Tuscan columns. Windows are one-over-one or single-light wood-sash windows, and surrounds are unmitered with a beaded edge on the second story. Other notable features include a hip-roof dormer, wide, overhanging eaves with a beaded-board soffit and a frieze panel underneath.

Individual Resource Status: **Single Dwelling**

Contributing

2910 23rd Street, North 000-5056-0185

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The three-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. The facade is faced with brick veneer on the front story and aluminum siding on the second story, and has a side-gable roof sheathed in asphalt shingles. The one-story, three-bay, shed-roof front porch has square posts. Windows are 6/6 wood-sash, set off by simulated shutters. Other notable features include rowlock sills on the first story.

Individual Resource Status: **Single Dwelling**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 35

2911 23rd Street, North 000-5056-0088

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1922**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in wood shingles and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame screened-in front porch on square battered posts with knee braces at the corners. Windows are both six-over-one and four-over-one wood-sash, and grouped into threes, with beaded wood surrounds. Other notable features include a shed-roof front dormer and wide, overhanging eaves with exposed rafter tails.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Garage**

Contributing

Contributing

2914 23rd Street, North 000-5056-0089

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1927**

The two-bay-wide, wood-frame dwelling rests on a solid parged brick masonry foundation. It is clad in lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on grouped Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are unmitered with a molded sill and lintel. Other notable features include a shed-roof dormer, wide, overhanging eaves with exposed, scroll-sawn rafter tails, and diamond-pattern wood shingles and triangular knee braces in the gable ends.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Garage**

Contributing

Non-Contributing

2917 23rd Street, North 000-5056-0090

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other, pre 1929**

The two-bay-wide, wood-frame four-square dwelling rests on a solid parged foundation. It is clad in narrow, lapped wood siding and has a hipped roof sheathed in pressed metal shingles. It has a one-story, two-bay, wood-frame front porch on square turned posts and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill and molded lintel. Other notable features include a hip-roof dormer with a tri-partite window, wide, overhanging eaves, and applied, non-functional wood louvered shutters.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Garage**

Contributing

Contributing

3201 23rd Street, North 000-5056-0091

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in asbestos shingles and has a front-gable roof sheathed in pressed metal shingles. It has a one-story, two-bay, wood-frame front porch on Tuscan columns and one-over-one wood-sash windows. Other notable features include an aluminum-clad cornice with gable returns, wide, overhanging eaves, affixed simulated louvered shutters, and one-story addition on the rear elevation, clad in weatherboard.

Individual Resource Status: **Single Dwelling**

Contributing

3202 23rd Street, North 000-5056-0092

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is stuccoed on the first story with wood shingles on the gable ends and dormers. It has a front-gable roof sheathed in wood shingles. It has a one-story, two-bay, wood-frame front porch in antis on robust square posts and six-over-one wood-sash windows. Window and door surrounds are beaded with a projecting sill. Other notable features include shed-roof side dormers, triangular knee braces and denticulation in the gable ends, and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Shed**

Contributing

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 36

3205 23rd Street, North 000-5056-0093

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1923**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation with a raised basement. It is clad in lapped wood siding on the first story and wood shingles on the dormers, and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting backband. Other notable features include a shed-roof dormer with a low balustrade, wide, overhanging eaves, and a vinyl cornice and soffit.

Individual Resource Status: **Single Dwelling**

Contributing

3206 23rd Street, North 000-5056-0094

Primary Resource Information: **Single Dwelling, Stories 1, Style: Bungalow/Craftsman, pre 1916**

The three-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in wood shingles and has a side-gable roof sheathed in asphalt shingles. It has a one-story, single-bay, shed-roof wood-frame front porch with robust, battered rubble piers, and nine-light wood casement windows. Window and door surrounds are beaded with a projecting sill. Other notable features include triangular knee braces and a rubble central interior chimney.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3209 23rd Street, North 000-5056-0095

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1917**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in lapped wood siding on the first story and wood shingles on the second story. It has a hipped roof sheathed in asphalt shingles, and a one-story, three-bay, wood-frame wrap-around front porch on square Tuscan posts. Windows are one-over-one wood-sash, with unmolded surrounds and a projecting sill. Other notable features include gable-roof dormers on each elevation and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

3210 23rd Street, North 000-5056-0096

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other, pre 1916**

The two-bay-wide, wood-frame dwelling rests on a solid brick parged foundation. It is clad in vinyl siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame shed-roof front porch on metal piers and one-over-one wood-sash windows. Window and door surrounds are aluminum. Other notable features include stone-facing on the first story underneath the porch, an aluminum box cornice, affixed simulated shutters on the front elevation, wide, overhanging eaves, and a single-cell addition to the east elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3213 23rd Street, North 000-5056-0097

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The two-bay-wide, wood-frame dwelling is clad in lapped wood siding on the first story and wood shingles on the second story. It has a hipped roof sheathed in pressed metal shingles, and a one-story, three-bay, wood-frame front porch on Tuscan columns. Windows are paired one-over-one vinyl-sash windows, with two four-light sash windows in the front dormer. Window and door surrounds feature projecting sills and molded lintel. Other notable features include wide, overhanging eaves and a one-story addition on the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 37

3214 23rd Street, North 000-5056-0098

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1927**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in lapped wood siding on the first story and wood shingles on the second story. It has a front-gable roof sheathed in asphalt shingles, and two hip-roof dormers. It has a one-story, three-bay, wood-frame front porch in antis on molded square posts and both one-over-one sash and diamond-paned fixed sash wood windows. Window and door surrounds are unmitered and molded. Other notable features include wide, flared overhanging eaves, a three-faceted bay window on the front elevation, a molded wood cornice, and a shed-roof screened in porch addition on the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3300 23rd Street, North 000-5056-0099

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, ca 1985**

The two-bay-wide, wood-frame dwelling rests on a solid foundation. It is clad in aluminum siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story, one-bay wood-frame front portico on square posts and one-over-one wood-sash windows. Other notable features include the projecting front elevation, a three-faceted bay window, applied simulated shutters, and a deck on the rear elevation.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Shed**

Non-Contributing

3304 23rd Street, North 000-5056-0100

Primary Resource Information: **Single Dwelling, Stories 2, Style: Tudor Revival, pre 1935**

The four-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in wood shingles and has a side-gable roof sheathed in asphalt shingles. It has both six-over-one wood-sash windows and six-light wood casement windows. Window and door surrounds feature molded lintels and projecting sills. Other notable features include a projecting front-gable flared roof vestibule with an arched entry and molded cornice with gable returns, the original Tudor revival door with heavy metal strap hinges, and hinged decorative louvered shutters.

Individual Resource Status: **Single Dwelling**

Contributing

3308 23rd Street, North 000-5056-0101

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1916**

The four-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in narrow lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and six-over-one wood-sash windows. Window and door surrounds have molded lintels and projecting sills. Other notable features include a hip-roof dormer with four-light wood-sash windows and clad wood shingles, wide, overhanging eaves and a rear one-story shed-roof addition.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3309 23rd Street, North 000-5056-0102

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in narrow lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and nine-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill and molded lintel. Other notable features include a hip-roof dormer with triangle-paned wood casement windows, wide, overhanging eaves with exposed scroll-sawn rafter tails, and hinged louvered wood shutters on the front elevation. The building is currently undergoing renovations which will include the construction of a large addition to the rear.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 38

3312 23rd Street, North 000-5056-0103

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1914**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in narrow lapped wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame wrap-around front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds feature a projecting sill and molded lintel. Other notable features include a closed gable end with wood shingles, a molded wood cornice with a blank frieze, and affixed decorative louvered shutters on the front elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

3317 23rd Street, North 000-5056-0104

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1918**

The two-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in narrow lapped wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, four-bay, wood-frame front porch on Tuscan columns and both nine-over-one and six-over-one wood-sash windows. Window and door surrounds feature molded lintels and projecting sills. Other notable features include wide, overhanging eaves with exposed scroll-sawn rafter tails, and wood shingles in the gable ends.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

3318 23rd Street, North 000-5056-0180

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The three-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in vinyl siding, and has a side-gable roof sheathed in asphalt shingles. The one-story, full-width front porch has turned posts and a projecting polygonal bay. Windows are 1/1 wood-sash, set off by unmolded aluminum surrounds. Other notable features include overhanging eaves and an aluminum soffit.

Individual Resource Status: **Single Dwelling**

Non-Contributing

3321 23rd Street, North 000-5056-0105

Primary Resource Information: **Single Dwelling, Stories 1, Style: Bungalow/Craftsman, pre 1925**

The three-bay-wide, wood-frame dwelling rests on a solid ashlar concrete-block foundation. It is clad in narrow lapped wood siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame front portico on battered square posts and six-over-one wood-sash windows. Other notable features include wide, overhanging eaves with exposed rafter tails, asbestos shingles in the gable end of the portico, egg-and-dart molding at the base of the portico piers, and a molded wood cornice.

Individual Resource Status: **Single Dwelling**

Contributing

3322 23rd Street, North 000-5056-0106

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1916**

The three-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in weatherboard and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on square turned posts and one-over-one wood-sash windows. Window and door surrounds feature a molded lintel and projecting sill. Other notable features include a gable-roof dormer with scroll-sawn decorative woodwork in the gable-end, wide, overhanging eaves with a wood soffit, and a wood cornice with blank frieze board.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 39

Lorcom Lane

2810 Lorcom Lane 000-5056-0116

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1935**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in asbestos shingles and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on square posts that has been enclosed and partially clad in asphalt shingles. The porch features metal jalousie windows. Windows are six-over-one wood-sash windows. Other notable features include a front-gable-roof dormer, wide, overhanging eaves with exposed rafter tails, and a molded wood cornice.

Individual Resource Status: **Single Dwelling**

Contributing

2900 Lorcom Lane 000-5056-0117

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1929**

The wood-frame dwelling is clad in perma-stone veneer and has a side-gable roof sheathed in asphalt shingles. It has a one-story, enclosed shed-roof wood-frame front porch, partially covered in perma-stone, with single-light casement windows. Windows elsewhere are four-over-one wood-sash windows. Other notable features include a shed-roof front dormer with exposed rafter tails, wide, overhanging eaves, and keystones over the windows.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

3310 Lorcom Lane 000-5056-0118

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1929**

The three-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in aluminum siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story, four-bay, wood-frame front porch on square posts and one-over-one vinyl-sash windows. Other notable features include affixed simulated shutters and a large two-story addition to the southeast corner of the building.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

North Edgewood Street

2320 North Edgewood Street 000-5056-0165

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1935**

The wood frame dwelling sits on a solid foundation and is capped by a hipped roof with asphalt shingles. The dwelling, clad in vinyl siding, measures three bays in width and features a central entry, inset two-bay porch with Tuscan post wood supports, overhanging eaves, and wood windows, including two 1/1 and two multi-light-over-one in the hipped dormer. Other details include square wood surrounds and sills, a solid balustrade, and a wide wood soffit.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 40

2324 North Edgewood Street 000-5056-0166

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, ca 1935**

The wood frame dwelling sits on a solid foundation and is capped by a side-gabled roof with asphalt shingles. The dwelling, clad in wood shingles, measures three bays in width and features a central entry, inset three-bay porch with wood post supports, overhanging eaves, and wood windows, including a fixed 6-light, three 1-light casements, and a 9/1. Other details include square wood surrounds and sills, an interior end brick chimney, and exposed rafters on the shed dormer.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Garage**

Contributing

Contributing

2325 North Edgewood Street 000-5056-0167

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, post 1956**

The concrete-block dwelling sits on a solid stuccoed foundation and is capped by a side-gabled roof with asphalt shingles. The building, which has a six-course Flemish bond facade, measures three bays in width and features a central entry, one-bay shed portico with wood post supports, replacement vinyl windows, an exterior end brick chimney, and rowlock sills.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2329 North Edgewood Street 000-5056-0168

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, post 1956**

The likely wood-frame dwelling, clad in six-course Flemish bond, sits on a solid concrete foundation and is capped by a side-gabled roof with asphalt shingles. The dwelling measures three bays in width and features a central entry, one-bay gabled portico with metal supports, two gabled wall dormers, an exterior end brick chimney, slightly overhanging eaves, and 6/6 wood windows. Other details include rowlock sills, weatherboard cladding in the portico peak, and a molded wood cornice.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Playhouse**

Non-Contributing

Non-Contributing

2330 North Edgewood Street 000-5056-0169

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other, pre 1935**

The four-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in vinyl siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, single-bay, shed-roof wood-frame front porch on square posts and six-over-one wood-sash windows. Window and door surrounds are unmolded with a projecting sill. Other notable features include wide, overhanging eaves and a complex roof line suggestive of remodeling.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Shed**

Contributing

Non-Contributing

2334 North Edgewood Street 000-5056-0119

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1914**

The two-bay-wide, wood-frame dwelling rests on a solid brick-stretcher foundation. It is clad in narrow lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are beaded with a projecting sill. Other notable features include a gable-roof dormer on each elevation with a molded cornice and gable-returns, wide, overhanging eaves with a blank frieze board beneath, a bay window on the south elevation, and a two-story addition to the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 41

North Fillmore Street

2111 North Fillmore Street 000-5056-0160

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1935**

The wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in lapped wood siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, shed-roof wood-frame front porch on Tuscan columns and six-over-one wood-sash windows. Window and door surrounds are beaded with a projecting sill. Other notable features include wide, shed-roof dormers and wide, overhanging eaves. The building has a strange window configuration on the ground floor where the original six-over-one windows are covered by two-over-two windows.

Individual Resource Status: **Single Dwelling**

Contributing

2301 North Fillmore Street 000-5056-0188

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The three-bay-wide, concrete-block masonry dwelling rests on a solid brick foundation. It is faced with 6:1 Flemish bond, and has a side-gable roof sheathed in asphalt shingles. The one-story, single-bay, shed-roof front porch has metal posts with an S-curve motif. Windows are 1/1 vinyl-sash, with one fixed single-light window. Other notable features include 2 front-gable dormers clad in vinyl siding, rowlock sills, a metal awning over the entry, and simulated louvered shutters.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2305 North Fillmore Street 000-5056-0161

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1923**

The wood-frame dwelling rests on a solid parged foundation. It is clad in narrow lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns with scroll-sawn brackets, and one-over-one wood-sash windows. Window and door surrounds are unmolded with a projecting sill. Other notable features include a hip-roof front dormer, a shed-roof porch on the southeast elevation, and a deck on the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

2322 North Fillmore Street 000-5056-0190

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other,**

The three-bay-wide, concrete-block masonry dwelling rests on a solid brick foundation. It is faced with 6:1 American bond, and has a side-gable roof sheathed in asphalt shingles. The one-story, single-bay, front-gable portico has metal posts with an S-curve motif. It has projecting 15-light vinyl fixed "garden" windows with false muntins, set off by projecting rowlock sills. Other notable features include a raised basement, simulated louvered shutters, and header sills.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2332 North Fillmore Street 000-5056-0191

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival,**

The three-bay-wide, concrete-block masonry dwelling rests on a solid brick foundation. It is faced with 6:1 Flemish bond, and has a side-gable roof sheathed in asphalt shingles. The one-story, single-bay, flat-roof hood over the entry is supported on metal brackets. Windows are 1/1 vinyl-sash, a diamond-paned casements. Other notable features include two front-gable dormers clad in aluminum siding, a raised basement accommodating a below-grade garage, a three-faceted bay window with a copper roof, a Colonial Revival entry surround with fluted pilasters, and rowlock sills. Major alterations include the one-story, gable-roof addition to the north.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Shed**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 42

2336 North Fillmore Street 000-5056-0192

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other, ca 2000**

The three-bay-wide, wood-frame four-square dwelling rests on a solid parged foundation. It is clad with wood shingles, and has a hipped roof sheathed in asphalt shingles. The one-story, three-bay, half-hip-roof front porch has square posts. Windows are 6/1 vinyl-sash, set off by unmolded wood surrounds. Other notable features include a hip-roof dormer with 4-light windows, a wood fascia, projecting eaves, and a wood soffit.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Garage**

Non-Contributing

2338 North Fillmore Street 000-5056-0162

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The wood frame American foursquare dwelling sits on a solid concrete foundation and is capped by a hipped roof with asphalt shingles and a central hipped dormer. The dwelling, clad in weatherboard and wood shingles, measures two bays in width and features an end-bay entry, two-bay porch with Tuscan column supports, overhanging eaves, and 1/1 and 1-light awning wood windows. Other details include beaded surrounds and sills, square balusters, louvered shutters, a beaded fascia board, and a Colonial Revival door surround.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

2342 North Fillmore Street 000-5056-0163

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1923**

The wood frame dwelling, which exhibits Colonial Revival inspired detailing, sits on a solid parged foundation and is capped by a front-gabled roof with asphalt shingles and an inset gabled dormer with overhanging eaves and a molded cornice with returns. The dwelling, clad in weatherboard, measures three bays in width and features a recessed entry, inset two-bay wrap porch with Tuscan column supports, overhanging eaves, an exterior end chimney, and two 12/1 wood windows. Other details include square-edged wood surrounds and sills, beaded lintels, and a boxed wood molded cornice.

Individual Resource Status:

Non-Contributing

Individual Resource Status: **Single Dwelling**

Contributing

2343 North Fillmore Street 000-5056-0164

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1923**

The wood frame dwelling sits on a solid foundation and is capped by a side-gabled roof with asphalt shingles and a large central gabled dormer with weatherboard cladding. The dwelling, clad in stucco, measures two bays in width and features an end-bay entry, three-bay porch with Tuscan post supports, overhanging eaves, and 6/1 wood windows. Other details include thin wood surrounds and sills, square balusters, exposed roof rafters, and a wood cornice.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 43

North Irving Street

2100 North Irving Street 000-5056-0158

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1916**

The wood-frame dwelling, oriented facing Old Dominion Drive, rests on a solid concrete-block foundation. It is stuccoed and has a front-gable roof sheathed in asphalt shingles. It has a one-story, five-bay, wood-frame front porch, supported by Tuscan columns on square piers, that wraps around both sides of the front elevation. Windows are primarily one-over-one vinyl-sash windows, with unmitered surrounds with a square-profile backband. Other notable features include wide, overhanging flared eaves with exposed scroll-sawn rafter tails, two gable-roof side dormers, a three-faceted bay window on the east elevation, and a molded wood cornice. Several additions have been built onto the west and rear elevations.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Shed**

Contributing

Non-Contributing

2102 North Irving Street 000-5056-0159

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in narrow lapped wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame wrap-around front porch on Tuscan columns currently undergoing repairs. Windows are one-over-one wood-sash windows, with a single-sash craftsman-style replacement window in the gable end. Window and door surrounds are unmitered and with a projecting sill and molded lintel. Other notable features include two gable-roof dormers on the side elevations, wide, overhanging eaves, a three-faceted bay window on the south elevation, diamond-shaped wood shingles and molded gable returns in the gable end, and a new copper standing-seam metal roof on the porch.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Garage**

Contributing

Contributing

North Jackson Street

2302 North Jackson Street 000-5056-0148

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1916**

The wood frame dwelling sits on a solid rock-faced concrete block foundation and is capped by a front-gabled roof with asphalt shingles. The dwelling, clad in stucco, measures three bays in width and features an end-bay entry, three-bay porch with wood Tuscan column supports, overhanging eaves, and 6/6, 6/1, and 9/1 windows. Other details include square wood surrounds and sills, an interior brick chimney, and a boxed aluminum cornice with returns. The dwelling shows a stylistic influence of the Queen Anne period with a wood shingled gable peak.

Individual Resource Status: **Single Dwelling**

Contributing

2304 North Jackson Street 000-5056-0149

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1915**

The wood frame dwelling sits on a solid concrete foundation and is capped by a cross-gabled roof with asphalt shingles and a shed dormer with 4-light casement windows. The dwelling, clad in wood shingles, measures three bays in width and features a central entry, two-bay inset porch with Craftsman supports, overhanging eaves, and 6/1 wood windows. Other details include 8-light sidelights, square balusters, Craftsman posts, square wood surrounds and sills, an exterior side brick chimney, and a wood cornice.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Shed**

Contributing

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 44

2309 North Jackson Street 000-5056-0183

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The two-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in vinyl siding, and has a front-gable roof sheathed in asphalt shingles. The one-story, single-bay, shed-roof front porch has turned posts. Windows are 1/1 wood-sash. Other notable features include a projecting front gable with wood fishscale shingles, projecting eaves, and a vinyl cornice and soffit.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2310 North Jackson Street 000-5056-0150

Primary Resource Information: **Single Dwelling, Stories 2, Style: Dutch Colonial Revival, pre 1916**

The wood frame dwelling sits on a solid, rock-faced concrete block foundation and is capped by a gambrel roof with asphalt shingles. The dwelling, clad in weatherboard and wood shingles, measures two bays in width and features an end-bay entry, three-bay porch with Tuscan column supports, overhanging eaves, and 6/1 and 6/6 wood windows. Other details include molded wood surrounds and sills, side elevation gabled dormers, paired windows, and a molded wood cornice.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

2313 North Jackson Street 000-5056-0151

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The wood frame dwelling sits on a solid stuccoed foundation and is capped by a hipped roof with asphalt shingles. The dwelling, clad in weatherboard and wood shingles, measures two bays in width and features a central half-hipped dormer, wide overhanging eaves, and wood windows, including three 1/1 and a 1-light casement. Other details include thin aluminum surrounds and sills, 1-light sidelights, and a boxed wood cornice.

Individual Resource Status: **Single Dwelling**

Contributing

2317 North Jackson Street 000-5056-0184

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The two-bay-wide, wood-frame dwelling rests on a solid brick foundation. It is clad with vinyl siding, and has a front-gable roof sheathed in asphalt shingles. The one-story, two-bay, half-hip-roof front porch has slender wood columns. Windows are 1/1 wood-sash, set off by louvered simulated shutters. Other notable features include a three-faceted bay window on the first story, unmolded wood window surrounds, a wood cornice with gable returns and projecting eaves.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2318 North Jackson Street 000-5056-0152

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Craftsman, ca 1923**

The wood frame bungalow, which features Colonial Revival detailing, sits on a solid, rock-faced concrete block foundation and is capped by a side-gabled roof with asphalt shingles and a central gabled dormer. The stucco-clad dwelling measures two bays in width and features an end-bay entry, a three-bay porch with Tuscan wood column supports, overhanging eaves, and 1/1 wood windows. Other details include square wood surrounds and sills, a central interior brick chimney, and a wood cornice.

Individual Resource Status: **Single Dwelling**

Contributing

2321 North Jackson Street 000-5056-0153

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1916**

The wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in narrow lapped wood siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on square posts. Windows are a combination of six-light wood casements, one-over-one wood-sash, and one-over-one vinyl-sash. Window and door surrounds have molded lintels. Other notable features include a shed-roof dormer, wide, overhanging eaves with exposed scroll-sawn rafter tails, and a large front-gable two-story addition that has been built onto the south elevation.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 45

2324 North Jackson Street 000-5056-0154

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in narrow lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame wrap-around front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are unmitered with a molded lintel. Other notable features include a hip-roof front dormer, wide, overhanging eaves with exposed rafter tails, and a series of irregular additions to the rear elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

Individual Resource Status: **Greenhouse**

Non-Contributing

2325 North Jackson Street 000-5056-0155

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other, pre 1916**

The two-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in narrow lapped wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are beaded with a projecting sill. Other notable features include two gable-roof dormers on the side elevations, wide, overhanging eaves with exposed rafter tails, a wood cornice with gable returns, and a very large addition onto the south elevation.

Individual Resource Status: **Single Dwelling**

Contributing

2326 North Jackson Street 000-5056-0156

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Craftsman, pre 1923**

The two-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in lapped wood siding and has a hipped roof sheathed in diamond-shaped asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and both one-over-one and six-light wood-sash windows. Window and door surrounds are unmolded with a projecting sill. Other notable features include a hip-roof front dormer with flared eaves, wide, overhanging flared eaves, and a wood soffit.

Individual Resource Status: **Single Dwelling**

Contributing

2330 North Jackson Street 000-5056-0157

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1927**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in lapped wood siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story, one-bay, gable-roof wood-frame front porch supported by square posts on brick piers and six-over-one wood-sash windows. Other notable features include a wide, overhanging eaves with exposed rafter tails and triangular knee braces on the gable ends.

Individual Resource Status: **Single Dwelling**

Contributing

North Kenmore Street

2101 North Kenmore Street 000-5056-0128

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, ca 1926**

The two-bay-wide, wood-frame dwelling rests on a solid ashlar concrete-block foundation. It is clad in narrow lapped wood siding and has a side-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and six-over-one wood-sash windows. Window and door surrounds are beaded with a projecting sill. Other notable features include two shed-roof dormers with paired windows, and wide, overhanging eaves with exposed rafter tails.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 46

2104 North Kenmore Street 000-5056-0176

Primary Resource Information: **Single Dwelling, Stories 3, Style: Other,**

The two-bay-wide, wood-frame dwelling rests on a solid concrete foundation, formed to simulate brick. It is clad in vinyl siding, and has a front-gable roof sheathed in asphalt shingles. The one-story, single-bay, front-gable portico has square posts. Windows are paired single-light vinyl casement set off by louvered simulated shutters on the second and garret stories, and on the first story is a three-faceted bay window with a large fixed plate-glass window flanked by two vinyl casements. Other notable features include an open gable with aluminum cornice returns, and an aluminum fascia.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2109 North Kenmore Street 000-5056-0129

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1915**

The wood-frame dwelling rests on a solid parged brick foundation and is clad in lapped wood siding. It has a side-gable roof sheathed in asphalt shingles, with a projecting three-faceted bay window capped by a front-gable. It has a one-story, wood-frame wrap-around front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are feature molded lintels and projecting sills.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

2110 North Kenmore Street 000-5056-0130

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1916**

Originally a two-story, wood-frame dwelling with a one-story front porch and a rectangular footprint, this building was radically remodeled during the third quarter of the twentieth century. It is now a two-story, two-bay, wood-frame house with a one-story, single-bay extension to the south. It is clad in brick veneer simulating Flemish bond, and has a hip roof clad in asphalt shingles. The extension has a jerkinhead roof also clad in asphalt shingles. Windows are six-over-six wood-sash windows, with rubbed brick surrounds and soldier-course lintels on the first story. The front entry is framed by a Colonial Revival neo-classical door surround with a broken pediment and finial, and four-light side-lights.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2200 North Kenmore Street 000-5056-0131

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1912**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in vinyl siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame wrap-around front porch on square posts and one-over-one vinyl-sash windows. Window and door surrounds have been obscured by the vinyl siding. Other notable features include a diamond-shaped single-light and gable returns in the gable end, and additions onto the rear and south elevations, and a porch enclosure.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Non-Contributing

2204 North Kenmore Street 000-5056-0132

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1912**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in asbestos siding and has a side-gable roof sheathed in pressed metal shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and one-over-one wood-sash windows. Other notable features include two gable-roof dormers, wide, overhanging eaves and applied simulated louvered shutters to the front elevation.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 47

2206 North Kenmore Street 000-5056-0133

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1923**

The three-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in asbestos siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, one-bay, wood-frame front porch on square turned posts with plain brackets, and one-over-one wood-sash windows. Window and door surrounds feature molded lintels. Other notable features include a hip-roof dormer and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Guest House**

Non-Contributing

2207 North Kenmore Street 000-5056-0134

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other,**

The three-bay-wide, wood-frame dwelling rests on a solid stretcher-bond brick foundation with a raised basement. It is executed in buff brick veneer and has a low-pitched front-gable roof sheathed in asphalt shingles. Windows are both paired six-over-six wood-sash and 12-light picture windows with two casement lights. Windows are set off by rowlock sills. Other notable features include a molded wood cornice, and applied wood louvered simulated shutters.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

2210 North Kenmore Street 000-5056-0135

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1916**

The two-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in asbestos siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame wrap-around front porch on Tuscan columns and one-over-one wood-sash windows. Window and door surrounds feature molded lintels. Other notable features include a hip-roof front dormer with two single-light wood windows, and wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

2211 North Kenmore Street 000-5056-0136

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The four-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in buff brick veneer and has a front-gable roof sheathed in asphalt shingles. Windows are two-by-two horizontal wood-sash windows with rowlock sills. Other notable features include applied wood louvered simulated shutters, wood siding in the gable end, a molded wood cornice with a blank frieze panel, and a contemporary-style front entry with a three-light, full-height transom and sidelights.

Individual Resource Status: **Single Dwelling**

Non-Contributing

Individual Resource Status: **Shed**

Non-Contributing

2213 North Kenmore Street 000-5056-0137

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1923**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in aluminum siding and has a hipped roof sheathed in standing-seam metal. It has a one-story, two-bay, wood-frame front porch on square turned posts with scroll-sawn brackets, and two-over-two wood-sash windows. Window and door surrounds are unmitered with a projecting sill. Other notable features include three shed-roof dormers, wide, overhanging eaves, and a one-story rear addition.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 48

2214 North Kenmore Street 000-5056-0138

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other, pre 1916**

The wood-frame dwelling rests on a solid brick stretcher foundation and has a T-shaped footprint. It is clad in lapped wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, shed-roof wood-frame front porch on turned posts on the south elevation, and one-over-one wood-sash windows. Other notable features include wide, overhanging eaves, an aluminum-clad box cornice, and applied louvered simulated shutters.

Individual Resource Status: **Single Dwelling**

Contributing

2300 North Kenmore Street 000-5056-0139

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1935**

The three-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in lapped wood siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, single-bay, wood-frame front porch on square posts and six-over-six wood-sash windows. Window and door surrounds are unmolded with a projecting sill. Other notable features include the grouping of porch supports into threes, a wood cornice, and a deck addition to the rear.

Individual Resource Status: **Single Dwelling**

Contributing

2301 North Kenmore Street 000-5056-0178

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other,**

The wood-frame ranch dwelling rests on a solid brick stretcher foundation. The lower half of the building is faced with stretcher bond brick, and the upper half is clad in vertical wood siding. It has a low-pitched side-gable roof sheathed in asphalt shingles. Windows are vinyl one-by-one-by-one horizontal sliding windows, or single-light vinyl casements. Other notable features include a sunroom on the east end and a wood cornice.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2302 North Kenmore Street 000-5056-0193

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other,**

The three-bay-wide, concrete-block masonry dwelling rests on a solid brick foundation. It is faced with 6:1 American bond, and has a front-gable roof sheathed in asphalt shingles. The one-story, three-bay, front-gable front porch has square wood posts. Windows are 2/2 wood-sash, set off by projecting header sills. Other notable features include vinyl siding on the porch and gable ends, and a raised basement.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2304 North Kenmore Street 000-5056-0140

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1923**

The three-bay-wide, wood-frame dwelling rests on a solid rock-face concrete-block foundation. It is clad in aluminum siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wood-frame front porch on Tuscan columns and twelve-over-twelve vinyl-sash windows. Window and door surrounds feature molded lintels. Other notable features include a hip-roof front dormer, wide, overhanging eaves with exposed scroll-sawn rafter tails, and a large addition to the rear of the building.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

2305 North Kenmore Street 000-5056-0179

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other,**

The wood-frame ranch dwelling rests on a solid brick stretcher foundation. It is faced with stretcher bond on the lower half, and vertical board on the upper half. It has a low-pitched side-gable roof sheathed in asphalt shingles. Windows are single-light vinyl casements and with two fixed single-light vinyl picture windows, flanked by simulated shutters. Other notable features include projecting eaves, a brick rowlock stringcourse, and an attached carport.

Individual Resource Status: **Single Dwelling**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 49

2309 North Kenmore Street 000-5056-0141

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other, pre 1937**

The two-bay-wide dwelling exhibits six-course American bond brick on the exterior, and rests on a solid brick foundation. It features a gable-front roof sheathed in asphalt shingles. It has a one-story, one-bay, front porch with square post wood supports and one-over-one vinyl-sash windows. Other notable features include rowlock sills, a corbeled brick chimney, and a shed-roof addition.

Individual Resource Status: **Single Dwelling**

Contributing

2310 North Kenmore Street 000-5056-0142

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1915**

The wood-frame dwelling sits on a solid foundation and is capped by a front-gable roof sheathed in asphalt shingles. The dwelling, clad in asbestos shingles on the first story and weatherboard on the second story, features an off-center entry, a three-bay porch on Tuscan columns, wide, overhanging eaves, and two one-over-one wood-sash windows. Other details include a closed tympanum with a pent roof, and a wood box cornice.

Individual Resource Status: **Single Dwelling**

Contributing

2311 North Kenmore Street 000-5056-0143

Primary Resource Information: **Single Dwelling, Stories 2, Style: Tudor Revival, pre 1937**

The three-bay-wide, wood-frame dwelling rests on a solid brick stretcher foundation. It is clad in brick veneer and weatherboard in the gable ends, and has a gable roof sheathed in asphalt shingles. It has a projecting off-center bay with a central entry, and 6/6 vinyl-sash windows. Windows have brick rowlock sills, and the round-arched front entry has rough stone rustication around it.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

2314 North Kenmore Street 000-5056-0144

Primary Resource Information: **Single Dwelling, Stories 3, Style: Colonial Revival, pre 1928**

The wood frame dwelling sits on a solid stuccoed foundation and is capped by a front-gabled roof with asphalt shingles. The dwelling, clad in asbestos shingles, measures four bays in width and features a two-bay porch on square posts, overhanging eaves, and six-over-one wood-sash windows. Other details include molded wood surrounds, an exterior-end brick chimney, and a molded wood cornice with gable-returns. The house is said to incorporate a circa 1908 house that was severely damaged by fire.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

2315 North Kenmore Street 000-5056-0145

Primary Resource Information: **Single Dwelling, Stories 2, Style: Tudor Revival, pre 1937**

The dwelling, exhibiting stretcher-bond brick on the exterior, sits on a solid brick foundation and is capped by a side-gabled roof with asphalt shingles. The dwelling, which features aluminum siding in the gable-end, is three bays in width and features a projecting central gabled entry and one-over-one vinyl-sash windows. Other details include thin aluminum surrounds and sills, an exterior-end brick chimney, and a flush aluminum cornice.

Individual Resource Status: **Single Dwelling**

Contributing

2317 North Kenmore Street 000-5056-0146

Primary Resource Information: **Single Dwelling, Stories 2, Style: Tudor Revival, pre 1937**

The dwelling sits on a solid brick foundation and is capped by a side-gabled roof with asphalt shingles. The dwelling, likely wood-frame with brick veneer, features vinyl siding in the gable ends. The building is three bays in width and features a projecting central gabled entry vestibule, exterior-end brick chimney, a rusticated stone and soldier arched brick door surround, and vinyl-sash one-over-one windows. Other details include thin aluminum surrounds and sills and a flush aluminum cornice.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 50

2318 North Kenmore Street 000-5056-0147

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other, pre 1923**

The wood frame dwelling sits on a solid concrete foundation and is capped by a hipped roof with asphalt shingles. The dwelling, clad in vinyl siding, measures three bays in width and features a slightly off-center entry, one-bay gabled porch with metal supports, overhanging eaves, and six-over-one vinyl-sash windows. Other details include aluminum surrounds and sills, a central interior brick chimney, and an aluminum box cornice.

Individual Resource Status: **Single Dwelling**

Individual Resource Status: **Garage**

Contributing

Non-Contributing

North Lincoln Street

2161 North Lincoln Street 000-5056-0125

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1918**

The wood-frame dwelling rests on a solid concrete-block foundation. It is clad in narrow lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on slender Tuscan columns and one-over-one wood-sash windows. Window and door surrounds are unmolded with a projecting sill. Other notable features include a hip-roof dormer, wide, overhanging eaves, a three-faceted bay window on the front elevation and a later, massive brick chimney on the south elevation.

Individual Resource Status: **Single Dwelling**

Contributing

2165 North Lincoln Street 000-5056-0171

Primary Resource Information: **Single Dwelling, Stories 2, Style: Other,**

The three-bay-wide, concrete-block masonry dwelling rests on a solid brick stretcher foundation. It is faced with stretcher bond, and has a side-gable roof sheathed in asphalt shingles. Windows are multi-light metal casements with four-light transoms. Other notable features include two front-gable dormers clad in aluminum siding.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2209 North Lincoln Street 000-5056-0127

Primary Resource Information: **Single Dwelling, Stories 2, Style: Colonial Revival, pre 1938**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in asbestos shingles and has a side-gable roof sheathed in asphalt shingles. It has a projecting front-gabled center section and six-over-six wood-sash windows. Window and door surrounds feature a projecting sill. Other notable features include an arched entryway leading to the front door, a molded wood cornice, and a series of very large additions to the rear.

Individual Resource Status: **Single Dwelling**

Contributing

2215 North Lincoln Street 000-5056-0172

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other,**

The wood-frame dwelling has four irregularly spaced bays and rests on a solid brick stretcher foundation. The lower portion of the facade is faced in stretcher bond brick, while the upper portion is clad in aluminum siding. It has a low-pitched, side-gable roof sheathed in asphalt shingles. The off-center entry is covered by a cantilevered hood capped by a small recessed gable. Windows are 1/1 vinyl-sash. Other notable features include simulated paneled shutters, a header string course, an aluminum cornice, and projecting eaves.

Individual Resource Status: **Single Dwelling**

Non-Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 51

2300 North Lincoln Street 000-5056-0082

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1912**

The three-bay-wide, brick masonry dwelling rests on a solid brick stretcher foundation. It is composed of five-course American bond has a hipped roof sheathed in pressed metal shingles. It has a one-story, three-bay, wood-frame front porch on wood columns and one-over-one wood-sash windows with three rows of arched headers in the lintels. Other notable features include a gable-roof dormer, wide, overhanging eaves, a corbeled brick cornice and a single-light transom over the front entry.

Individual Resource Status: **Single Dwelling**

Contributing

2301 North Lincoln Street 000-5056-0173

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other,**

The wood-frame dwelling has four irregularly spaced bays and rests on a solid brick stretcher foundation. The lower portion of the facade is faced in stretcher bond brick, while the upper portion is clad in vinyl siding. It has a low-pitched, side-gable roof sheathed in asphalt shingles, and 1x1 horizontal sliding windows. Other notable features include a header string course, projecting eaves, vinyl window surrounds and a vinyl cornice.

Individual Resource Status: **Single Dwelling**

Non-Contributing

2305 North Lincoln Street 000-5056-0174

Primary Resource Information: **Single Dwelling, Stories 1, Style: Other,**

The wood-frame dwelling has four irregularly spaced bays and rests on a solid brick stretcher foundation. The lower portion of the facade is faced in stretcher bond brick, while the upper portion is clad in vinyl siding. It has a low-pitched, side-gable roof sheathed in asphalt shingles. The off-center entry is covered by a one-story, one-bay portico with square posts. The house has 1x1 and tripartite vinyl horizontal sliding windows. Other notable features include simulated vernacular shutters, a header string course, projecting eaves and a vinyl cornice.

Individual Resource Status: **Single Dwelling**

Non-Contributing

North Monroe Street

2124 North Monroe Street 000-5056-0123

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1911**

The two-bay-wide, wood-frame dwelling is clad in aluminum siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, three-bay, wrap-around wood-frame front porch on square posts and one-over-one wood-sash windows. Window and door surrounds are clad in aluminum. Other notable features include a hip-roof dormer, wide, overhanging eaves and a large two-story addition to the north elevation of the building.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

Individual Resource Status: **Shed**

Non-Contributing

2130 North Monroe Street 000-5056-0124

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1911**

The three-bay-wide, wood-frame dwelling rests on a solid concrete-block foundation. It is clad in vinyl siding and has a front-gable roof sheathed in pressed metal shingles. It has a one-story, three-bay, wood-frame front porch on square turned posts and one-over-one vinyl-sash windows. Other notable features include diamond wood shingles and a square single-light window in the front gable end, wide, overhanging eaves, and extensive additions to the south and rear elevations.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 52

North Nelson Street

2200 North Nelson Street 000-5056-0121

Primary Resource Information: **Single Dwelling, Stories 3, Style: Queen Anne, pre 1914**

The two-bay-wide, wood-frame dwelling rests on a solid parged foundation with a raised basement and an L-shaped footprint. It is clad in aluminum siding and has a front-gable roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on square turned posts and one-over-one vinyl-sash replacement windows. Window and door surrounds are unmitered and unmolded with a projecting sill. Other notable features include a boxed aluminum cornice, a diamond-light in the garret story gable end, and a single-cell addition to the rear elevation, supported on two Tuscan columns.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Garage**

Contributing

2210 North Nelson Street 000-5056-0122

Primary Resource Information: **Single Dwelling, Stories 2, Style: Queen Anne, pre 1915**

The two-bay-wide, wood-frame dwelling is clad in aluminum siding and has a front-gable roof sheathed in asphalt shingles. It has an L-shaped footprint. It has a one-story, four-bay, wood-frame front porch on square turned posts and two-over-two wood-sash windows. Other notable features include wide, overhanging eaves, aluminum-clad gable returns in the gable end, applied simulated louvered shutters and a large rear addition.

Individual Resource Status: **Single Dwelling**

Contributing

North Oakland Street

2140 North Oakland Street 000-5056-9000

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1936**

The three-bay-wide dwelling rests on a solid brick stretcher foundation. It is currently being renovated, a process which has included the demolition of the front exterior brick wall and porch. It is clad in lapped wood siding and has a side-gable roof sheathed in asphalt shingles. Windows are two-over-two wood-sash. Other notable features include two shed-roof dormer, wide, overhanging eaves with exposed rafter tails, a wood molded cornice and a large rear addition.

Individual Resource Status: **Single Dwelling**

Contributing

Individual Resource Status: **Shed**

Non-Contributing

Old Dominion Drive

3209 Old Dominion Drive 000-5056-0001

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1929**

The two-bay-wide, wood-frame dwelling rests on a solid, rock-face concrete-block foundation and has a raised basement. It is clad in lapped wood siding and has a hipped roof sheathed in asphalt shingles. It has a one-story, two-bay, wood-frame front porch on square posts and nine-over-one wood-sash windows. Window and door surrounds are unmitered with a projecting sill. Other notable features include a hip-roof dormer, wide, overhanging eaves with exposed rafter tails, and a one-story, single-pile rear addition.

Individual Resource Status: **Single Dwelling**

Contributing

**United States Department of the Interior
National Park Service**

**NATIONAL REGISTER OF HISTORIC PLACES
Continuation Sheet**

MAYWOOD HISTORIC DISTRICT, ARLINGTON COUNTY, VA (VDHR 000-5056)

Section number 7 **Page** 53

3213 Old Dominion Drive 000-5056-0002

Primary Resource Information: **Single Dwelling, Stories 2, Style: Bungalow/Craftsman, pre 1929**

The two-bay-wide, wood-frame dwelling rests on a solid, rock-face concrete-block foundation and has a raised basement. It is clad in vinyl siding and has a gable roof sheathed in asphalt shingles. It has a one-story, four-bay, wood-frame front porch on square posts and six-over-six wood-sash windows. Window and door surrounds are unmitered and unmolded. Other notable features include a wood cornice with cyma molding.

Individual Resource Status: **Single Dwelling**

Contributing

Vacation Lane

3650 Vacation Lane 000-5056-0120

Primary Resource Information: **Single Dwelling, Stories 1, Style: Colonial Revival, pre 1929**

The three-bay-wide, wood-frame dwelling rests on a solid parged foundation. It is clad in aluminum and vinyl siding and has a jerkinhead roof sheathed in asphalt shingles. It has a one-story, one-bay, arched wood-frame front portico on square posts with a keystone in the pediment. Windows are six-over-one wood-sash and surrounds are unmitered with a projecting sill. Other notable features include wide, overhanging eaves.

Individual Resource Status: **Single Dwelling**

Contributing

Total Number of Resources: 193